

MACP-009596-CA0160

Broj dela:

MACP-009596-CA0160

Proizvođač / robna marka:

Aeroflex (MACOM Technology Solutions)

Opis proizvoda

RF DIR COUPLER 5MHZ-1GHZ SM22

Datasheets:

 MACP-009596-CA0160.pdf

Status RoHS

 Bez olova / RoHS Compliant

Stanje zaliha

27221 pcs stock

Ship From

hong kong

Shipment Way

DHL/Fedex/TNT/UPS/EMS




Solutions



Slika može biti reprezentativna. Pogledajte specifikacije za detalje o proizvodu.













Specifikacije MACP-009596-CA0160

| | |
|----------------------------------|--|
| BROJ DELA | MACP-009596-CA0160 |
| PROIZVOĐAČ | Aeroflex (MACOM Technology Solutions) |
| OPIS | RF DIR COUPLER 5MHZ-1GHZ SM22 |
| STATUS BEZ VODE / ROHS STATUS | Bez olova / RoHS Compliant |
| DOSTUPNA KOLIČINA | 27221 pcs |
| TEHNIČKI LIST |  MACP-009596-CA0160.pdf |
| PAKET UREDAJA ZA DOBAVLJAČE | SM-22 |
| SERIES | - |
| POVRATAK GUBITKA | -16dB |
| SNAGA - MAKS | - |
| PAKOVANJE | Cut Tape (CT) |
| PAKET / SLUČAJ | 6-SMD Module |
| DRUGE NAZIVE | 1465-1321-1 |
| NIVO OSETLJIVOSTI NA VLAGU (MSL) | 1 (Unlimited) |
| STATUS BEZ VODE / ROHS STATUS | Lead free / RoHS Compliant |
| IZOLACIJA | - |
| GUBITAK UMETANJA | - |
| FREKVENCIJA | 5MHz ~ 1GHz |
| DETALJAN OPIS | RF Directional Coupler 5MHz ~ 1GHz 10dB 6-SMD Module |
| FAKTOR SPAJANJA | 10dB |
| TIP SPOJNICE | Standard |
| APLIKACIJE | - |

Povezane oznake

| | | |
|--|---|---|
| Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160 | MACP-009596-CA0160 Distributor | MACP-009596-CA0160 Supplier |
| MACP-009596-CA0160 Cijena | MACP-009596-CA0160 Pictures | Slika MACP-009596-CA0160 |
| MACP-009596-CA0160 PDF Datasheet | MACP-009596-CA0160 Preuzimanje Datasheet | MACP-009596-CA0160 Datasheet |
| MACP-009596-CA0160 Stock | Kupi MACP-009596-CA0160 | Kupi Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160 |
| Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160 | Aeroflex (MACOM Technology Solutions) Supplier | Aeroflex (MACOM Technology Solutions) Distributor |
| Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160 | Aeroflex Circuit Technology MACP-009596-CA0160 | Aeroflex MACP-009596-CA0160 |
| Aeroflex (MACOM Technology Solutions) MACP-009596-CA0160 | Aeroflex Metelics, Division of MACOM MACP-009596-CA0160 | M/A-Com Technology Solutions MACP-009596-CA0160 |
| Metelics (MACOM Technology Solutions) MACP-009596-CA0160 | MACOM Technology Solutions MACP-009596-CA0160 | |

Srodni proizvodi

| | |
|---|--|
|  <p>MACP-008125-CK07TB Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: EVAL BOARD FOR MACP-008125-CK07F In stock: 555 pcs</p> <p>RFQ</p> |  <p>MACP-010507-CH0160 Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: RF DIR COUPLER 5MHZ-300MHZ 5SMD In stock: 75562 pcs</p> <p>RFQ</p> |
|  <p>MACP-008125-CK07F0 Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: RF DIR COUPLER 5MHZ-1GHZ SM127 In stock: 3506 pcs</p> <p>RFQ</p> |  <p>MACP-009596-CA01TB Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: EVAL BOARD FOR MACP-009596-CA016 In stock: 485 pcs</p> <p>RFQ</p> |
|  <p>MACP-007727-CI07B0 Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: RF DIR COUPLER 5MHZ-1.2GHZ SM123 In stock: 55152 pcs</p> <p>RFQ</p> |  <p>MACP-009730-C60370 Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: RF DIR COUPLER 5MHZ-1.2GHZ MOD In stock: 68058 pcs</p> <p>RFQ</p> |
|  <p>MACH102-8TP-R Proizvođači: Belden's Hirschmann Opis: NETWORK SWITCH-MANAGED 8 PORT In stock: 60 pcs</p> <p>RFQ</p> |  <p>MACP-010561-000000 Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: RF DIR COUPLER 2GHZ-6GHZ 6TDFN In stock: 4788 pcs</p> <p>RFQ</p> |
|  <p>MACP-009011-C80370 Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD In stock: 29238 pcs</p> <p>RFQ</p> |  <p>MACP-010414-CA0370 Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD In stock: 103049 pcs</p> <p>RFQ</p> |
|  <p>MACP-007727-CI07TB Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: EVAL BOARD FOR MACP-007727-CI07B In stock: 583 pcs</p> <p>RFQ</p> |  <p>MACP-010250-C808A0 Proizvođači: Aeroflex (MACOM Technology Solutions) Opis: RF DIR COUPLER 5MHZ-1.2GHZ MOD In stock: 114443 pcs</p> <p>RFQ</p> |